

# CERTIFICATE OF INSPECTION FOR VEHICLES UNDER 4,500 KG

Vehicle Safety  
J.W. Zacharias Physical Damage  
Research Centre  
1981 Plessis Road  
Box 45064  
Winnipeg, MB R2C 5C7



02642906

Date Inspection Started: DAY 27 MO. 09 YR. 18  
Date Inspection Completed: DAY MO. YR.  
Inspection Expiry Date: DAY MO. YR.

Inspection Result:  
 Pass/Safe Vehicle  
 Fail/Unsafe Vehicle  
 Fail/Out-of-Service

Address: \_\_\_\_\_ City: \_\_\_\_\_ Province: \_\_\_\_\_ Postal Code: \_\_\_\_\_  
Licence Number: \_\_\_\_\_ V.I.N./Serial Number: 1FTJW1EV2AF134104  
Odometer Reading: 159651  km  mi Prov. MB Make Ford Model F150 Year 10

DRIVER'S CONTROLS				
No.	R	C	Item	Ref #
01			Vehicle Identification Number	1-1, M1-1
02			Neutral Safety Switch	1-6
03			Accelerator Pedal	1-2
04			Sun Visors	8-13
05			Horn Operation	5-4, M5-2
06	X		Mirrors	8-11, 12, M5-3
07			Windshield Wipers and Washers	8-9
08			Defroster & Int. Heaters	8-14, 15
09			Speedometer, Odometer	5-1, 2, M5-4
10	X		Windshield and Windows	8-8, 10, M8-4
11			Switches	7-3, M7-3
12			Clutch and Brake Pedal Pad	5-5
13			Instrument Panel Lamps	6-3
14	X		Parking Brake, Transmission	3-1, 5-3, M1-4
15			Power Brake Operation	3-7
16			Brake Failure Indicators	3-3
17			Brake Pedal Reserve	3-4, 5, M3-2
18			Steering Lash & Travel	4-1, 2
19			Clutch Disengagement	1-5
20			Handlebars	M4-1

No.	R	C	Item	Ref #
31	X		Stop Lamps	6-1
32	X		Hazard Lamps	6-1
33			Daytime Running Lamps	6-1
34	X		Body & Bumpers	8-2, 4
35			Trunk	8-19
36			Doors and Door Latches	8-7
37			Kickstand	M8-5

ENGINE COMPARTMENT				
No.	R	C	Item	Ref #
61			Hood and Safety Catch	8-1
62			Wiring and Battery	7-1, 2, M7-1,2
63			Vacuum/Hydraulic System	3-6, 8
64			Brake Master Cylinder	3-2
65			Power Steering	4-8

UNDERCARRIAGE				
No.	R	C	Item	Ref #
38			Flooring	8-5
39			Kingpins	4-5
40			Tires, Wheels & Road Clearance	9-1 to 6, 2-9, M9-1, 2
41	X		Ball Joints	4-6, 7
42			Steering Linkage	4-3
43			Steering Column Coupler	4-4
44			Frame & Unibody	8-3, 6, M8-1
45			Spring and Attachments	2-1, 2, 3, M2-2
46	X		Shock Absorbers	2-5
47			Brake Lines & Hoses	3-2, M3-3
48			Wheel Bearings	2-6, 2-7, M2-1
49			Fuel System	1-3, M1-2
50			Exhaust System	1-4, M1-3
51	X		MacPherson Strut	2-4
52			Constant Velocity Joints	2-8

PROPANE/NATURAL GAS				
No.	R	C	Item	Ref #
66			Structural Members	1-10, 2-10
67			Pressure Vessel	1-2, 2-2
68			Damage Protection	1-6, 2-4
69			Corrosion Protection	1-6, 2-5
70			Pressure Vessel Filler & Interconnection	1-3
71			Main Shut-off Valve	1-4
72			Valves	1-8
73			Vaporizer	1-9
74			System Piping and Fittings	1-7, 2-7
75			Gas Safety Branch Decal	1-1, 2-1
76			Relieving Device (Burst Disc)	2-3
77			Pressure Gauge	2-6
78			Gasoline Lock-off	2-9
79			Pressure Regulator	2-8

BODY INTERIOR				
No.	R	C	Item	Ref #
21			Lamps	6-1, M5-1, M6-1
22			Seats and restraint systems	8-16 to 18, M8-2

BODY EXTERIOR				
No.	R	C	Item	Ref #
23			Headlamp, Operation	6-1
24			Headlamp Aim	6-4, M6-3
25	X		Turn Signal Lamps	6-1
26	X		Parking Lamps	6-1
27			Side Marker Lamps	6-1
28			Reflex Reflectors	6-2
29			Back-up Lamps	6-1
30	X		Tail Lamps	6-1

BRAKES				
No.	R	C	Item	Ref #
53	X		Front and Rear Disc Brakes	3-10
54	X		Front Brake Drums	3-9
55			Rear Brake Drums	3-9
56	X		Front Brake Lining	3-9
57	X		Rear Brake Lining	3-9
58	X		Wheel Cylinders	3-9, M3-3
59			Mechanical Components	3-8, 9, M3-1
60			Proportioning Valve	3-11

RECREATIONAL VEHICLE				
No.	R	C	Item	Ref #
80			CSA Z-240 Standard Approval Number	11-1
81			Manitoba Labour Z-240 Standard Approval Number	11-1

Brake Lining Thickness:   Drum/Rotor Measurement:   Right  
Axle 1  Axle 2  Axle 1  Axle 2  Left

**- THIS INSPECTION IS NOT A WARRANTY -**  
This inspection addresses safety components within the Provincial Vehicle Inspection Handbook but does not guarantee these components will comply with the standards for any unspecified future period of time.  
To determine if this vehicle has an open safety recall issued by the vehicle manufacturer, please search the Motor Vehicle Safety Recalls Database on Transport Canada's website at <http://www.tc.gc.ca/> or contact Transport Canada at 1-800-333-0510.

REMARKS: 10 Windshield Leaks

Mark 'X' under 'R' when item rejected  
Mark 'XX' under 'R' when vehicle out-of-service  
Mark 'X' under 'C' when item corrected  
Ref # indicates corresponding manual section  
A circled item # indicates advisement only

I am aware that the above-noted vehicle is unsafe to be operated on a highway due to the noted equipment defects. I undertake to prevent this vehicle from being operated on a highway until the repairs or adjustments have been made to restore it to safe condition and a qualified mechanic has re-inspected the vehicle.  
Vehicle Received without repairs by: \_\_\_\_\_ Signature \_\_\_\_\_ Date \_\_\_\_\_