



Note: In October 2018, CARPROOF Corporation will change its name to CARFAX Canada. For details, click [here](#).

VEHICLE HISTORY REPORT

CARPROOF Claims



VEHICLE DETAILS:
VIN: 1FTRX14W67FB32405
Year/Make/Model: 2007 FORD F150
Body Style: PICKUP
Country of Assembly: United States
Cylinders: 8
Fuel Type: Gas

REPORT DETAILS:
Report Number: 20762348
Report Date: 8/14/2018 11:20 AM EST
Report Status: Complete

REPORT SUMMARY

	Accidents / Damage:	Damage records found
	Canadian Registration:	Alberta (Normal) Northwest Territories (Normal)
	Stolen Status:	Not actively declared stolen
	U.S. History:	No U.S. history found
	Recalls:	No information available
	Service History:	2 record(s) found

QUESTIONS?

WE'RE HERE TO HELP.

CALL
1.866.835.8612

EMAIL
support@carproof.com



Report Findings in Chronological Order

CARPROOF

Below are all records for the vehicle, listed in the order that they occurred.

Date	Location	Data Source	Type of Record	Detail	Odometer
05/22/2008	Northwest Territories, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
05/22/2008	Northwest Territories, Canada	Motor Vehicle Dept.	Canadian Renewal	First Owner Reported	
11/01/2008			Collision		
05/27/2009	Northwest Territories, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
08/11/2009	Canada	Insurance Records	Collision claim		
01/03/2010			Collision		
01/27/2010	Peace River, Alberta, Canada	Insurance Records	Vehicle Valuation		101,667 KM
01/27/2010	Peace River, Alberta, Canada	Insurance Records	Estimate	FRONT CENTER	
01/16/2012	Northwest Territories, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
08/18/2012	Northwest Territories, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
09/04/2014	Northwest Territories, Canada	Motor Vehicle Dept.	Canadian Renewal	New Owner Reported	
09/04/2014	Northwest Territories, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
03/17/2015	High Level, Alberta, Canada	Recovery Automotive Ltd	Service Record	Vehicle serviced	141,516 KM
03/17/2015	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
07/29/2015	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
12/20/2016	High Level, Alberta, Canada	Recovery Automotive	Service Record	Vehicle serviced	

Date	Location	Data Source	Type of Record	Detail	Odometer
04/28/2017	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	
07/08/2017	Alberta, Canada	Motor Vehicle Dept.	Canadian Renewal	Registration Issued or Renewed	

Accident, Collision and Damage Detail CARPROOF

If the vehicle has had any history of accidents, collisions or damage in either Canada or the U.S., the records are outlined in this section.

VIN: 1FTRX14W67FB32405

Police Reported Accidents

Incident Date	Location	Detail
No police reported accidents found		

Accident/Damage Estimates

Accident estimate records are generated by collision estimating facilities from the process of estimating the amount and extent of damage to a vehicle. Estimates in some cases have associated insurance claims.

Incident Date	Location	Estimate Date	Type of Record	Detail	Amount	Odometer
01/03/2010	Peace River, Alberta, Canada	01/27/2010	Vehicle Valuation		\$0.00	101,867 KM
01/03/2010	Peace River, Alberta, Canada	01/27/2010	Estimate	FRONT CENTER	\$11,615.00	

Insurance Claims

The insurance claims identified in this report do not include any medical pay-outs, damage to other vehicles, damage to property, towing, rental cars, or any other incidental damages.

Incident Date	Location	Type of Claim	Detail	Amount	Odometer
11/01/2008		Collision		\$0.00	
08/11/2009	Canada	Collision claim		\$0.00	
01/03/2010		Collision		\$14,700.00	

Other Damage Records

Record Date	Location	Type of Record	Detail	Odometer
No other damage records found				

Canadian Registration CARPROOF

This section details where in Canada the vehicle is now or has ever been registered, as well as the status (Inspection Required, Normal, Non-repairable, Rebuilt, Salvage, Stolen) of the vehicle in those jurisdictions.

Jurisdiction	Branding	Detail
Alberta	NORMAL	This vehicle has been registered as Normal in this jurisdiction.
British Columbia	Not found	
Manitoba	Not found	
New Brunswick	Not found	
Newfoundland	Not found	
Nova Scotia	Not found	
Northwest Territories	NORMAL	This vehicle has been registered as Normal in this jurisdiction.
Nunavut	Not found	
Ontario	Not found	
Prince Edward Island	Not found	
Quebec	Not found	
Saskatchewan	Not found	
Yukon Territories	Not found	

Stolen Vehicle Check CARPROOF

This section outlines data from the Canadian Police Information Centre (CPIC), which is operated by the RCMP under the stewardship of National Police Services, on behalf of the Canadian law enforcement community.

Stolen Vehicle Check

Not declared stolen.



Import Records

CARPROOF

If the vehicle has been imported, you will find the details below.

Import Records

No vehicle import records found



United States Vehicle History

CARPROOF

In addition to information about the vehicle's history in Canada, CARPROOF also searches for information about the vehicle's history in the United States. If we discover any events in the U.S., you will find them below. Details about accidents, collisions and damage, or any import records will appear in the preceding sections of your report.

U.S. History Records

No U.S. history records found



Recalls

CARPROOF

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact FORD or visit Ford's website.



Service History

CARPROOF

These are records of service performed on the vehicle. These are the records reported to CARPROOF when this report was run – It is possible that service has occurred that is not captured here.

Date	Address	Data Source	Type of Record	Detail	Odometer
03/17/2015	High Level, Alberta, Canada	Recovery Automotive Ltd	Service Record	Safety inspection performed Exhaust repaired Ignition coil(s) replaced	141,516 KM
12/20/2016	High Level, Alberta, Canada	Recovery Automotive	Service Record	Drivability/performance checked No-start/hard start condition checked	

CARPROOF® Copyright 2005-2018 CARPROOF. All rights reserved.

Information on Reports

This vehicle history report is compiled from multiple data sources. It is not always possible for CARPROOF or its source data providers to obtain complete information on any one vehicle. For example, there may be other title brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARPROOF and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARPROOF, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARPROOF and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of fitness, accuracy, merchantability, mechanical quality or fitness for a particular purpose regarding this report or its contents. Neither CARPROOF nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARPROOF's Conditions of Use and any CARPROOF End User License Agreements as each may be amended from time to time by CARPROOF.

Conditions of Use



**Manitoba Société d'assurance
Public publique
Insurance du Manitoba**

Main Floor - 234 Donald Street
Rez-de-chaussée - 234, rue Donald
Box 6300 / C.P. 6300
Winnipeg, MB R3C 4A4
985-7000
www.mpi.mb.ca

Insurance Certificate
Certificat D'assurance

NO INSURANCE / PAS D'ASSURANCE

4216

OWNERSHIP DOCUMENT ONLY. NO REGISTRATION OR INSURANCE IN EFFECT. MOTOR VEHICLE LIABILITY INSURANCE CARD IS VOID.

DOCUMENT DE PROPRIÉTÉ SEULEMENT. PAS D'IMMATRICULATION ET PAS D'ASSURANCE. CARTE D'ASSURANCE RESPONSABILITÉ DU VÉHICULE EST ANNULÉ.



Registration Class:
Classe d'immatriculation:
Plate No. / N° de plaque:
Policy No. / N° de police:
Effective / Entrée en vigueur:
Expiry / Expiration:

Registered To / Insured By:
Immatriculé et assuré au nom de:

NO REGISTRATION / PAS D'IMMATRICULATION

(RRF):
(FTI):

MPI Use:
Réservé à la Société:

11353
091910

PRP %:

X

Signature / Signature:

Document Number: 25362102
N° de document:
Issue Date: September 19, 2018
Date de délivrance:
Registered Vehicle: 2007 FORD F150 XLS SUPERCAB
Véhicule immatriculé: Extended Cab 6 CYL, GRAY

Serial Number: 1FTRX14W67FB32405 4139898
N° de série:
Odometer Reading: 180549 KM As of: September 19, 2018
Lecture de l'odomètre: Date du relevé:
Owners / Propriétaires:
KOBI'S AUTO LTD

This vehicle requires a new Certificate of Inspection prior to registration.
Le véhicule exige un nouveau Certificat d'inspection avant de pouvoir être immatriculé.

CERTIFICATE OF INSPECTION FOR VEHICLES UNDER 4,500 KG

Vehicle Safety
J.W. Zacharias Physical Damage
Research Centre
1981 Plessis Road
Box 45064
Winnipeg, MB R2C 5C7

Manitoba



02568182

Date Inspection Started: DAY 09, MO. 10, YR. 19
 Date Inspection Completed: DAY 09, MO. 10, YR. 19
 Inspection Expiry Date: DAY 09, MO. 10, YR. 19

TYPE OF VEHICLE: Motorcycle Truck Passenger Car Recreational Vehicle NEW USED

Station Number: A5534 Station Name: Kobi's Auto City: _____
 Mechanic Number: _____ Mechanic Signature: _____ Station Phone Number: 1045922900

Vehicle Owner: _____

Inspection Result:
 Pass/Safe Vehicle
 Fail/Unsafe Vehicle
 Fail/Out-of-Service

Address: _____ City: _____ Province: _____ Postal Code: _____ Phone: _____
 Licence Number: _____ V.I.N./Serial Number: IF TRX14W67FB32405
 Odometer Reading: 180577.4 km mi Prov. MB Make Ford Model F150 Year 07

DRIVER'S CONTROLS				
No.	R	C	Item	Ref #
01			Vehicle Identification Number	1-1, M1-1
02			Neutral Safety Switch	1-6
03			Accelerator Pedal	1-2
04			Sun Visors	8-13
05			Horn Operation	5-4, M5-2
06			Mirrors	8-11, 12, M5-3
07			Windshield Wipers and Washers	8-9
08			Defroster & Int. Heaters	8-14, 15
09			Speedometer, Odometer	5-1, 2, M5-4
10	X		Windshield and Windows	8-8, 10, M6-4
11			Switches	7-3, M7-3
12			Clutch and Brake Pedal Pad	5-5
13			Instrument Panel Lamps	6-3
14			Parking Brake, Transmission	3-1, 5-3, M1-4
15			Power Brake Operation	3-7
16			Brake Failure Indicators	3-3
17			Brake Pedal Reserve	3-4, 5, M3-2
18			Steering Lash & Travel	4-1, 2
19			Clutch Disengagement	1-5
20			Handlebars	M4-1

No.	R	C	Item	Ref #
31	X		Stop Lamps	6-1
32			Hazard Lamps	6-1
33			Daytime Running Lamps	6-1
34			Body & Bumpers	8-2, 4
35			Trunk	8-19
36			Doors and Door Latches	8-7
37			Kickstand	M8-5

ENGINE COMPARTMENT				
No.	R	C	Item	Ref #
61			Hood and Safety Catch	8-1
62	X	X	Wiring and Battery	7-1, 2, M7-1,2
63			Vacuum/Hydraulic System	3-6, 8
64			Brake Master Cylinder	3-2
65			Power Steering	4-8

UNDERCARRIAGE				
No.	R	C	Item	Ref #
38			Flooring	8-5
39			Kingpins	4-5
40	O	O	Tires, Wheels & Road Clearance	9-1 to 6, 2-9, M9-1, 2
41			Ball Joints	4-6, 7
42	X		Steering Linkage	4-3
43			Steering Column Coupler	4-4
44			Frame & Unibody	8-3, 6, M8-1
45	X		Spring and Attachments	2-1, 2, 3, M2-2
46	X		Shock Absorbers	2-5
47	X		Brake Lines & Hoses	3-2, M3-3
48			Wheel Bearings	2-6, 2-7, M2-1
49			Fuel System	1-3, M1-2
50	X		Exhaust System	1-4, M1-3
51			MacPherson Strut	2-4
52			Constant Velocity Joints	2-8

PROPANE/NATURAL GAS				
No.	R	C	Item	Ref #
66			Structural Members	1-10, 2-10
67			Pressure Vessel	1-2, 2-2
68			Damage Protection	1-6, 2-4
69			Corrosion Protection	1-6, 2-5
70			Pressure Vessel Filler & Interconnection	1-3
71			Main Shut-off Valve	1-4
72			Valves	1-8
73			Vaporizer	1-9
74			System Piping and Fittings	1-7, 2-7
75			Gas Safety Branch Decal	1-1, 2-1
76			Relieving Device (Burst Disc)	2-3
77			Pressure Gauge	2-6
78			Gasoline Lock-off	2-9
79			Pressure Regulator	2-8

BODY INTERIOR				
No.	R	C	Item	Ref #
21			Lamps	6-1, M5-1, M6-1
22			Seats and restraint systems	8-16 to 18, M6-2

BRAKES				
No.	R	C	Item	Ref #
53	X		Front and Rear Disc Brakes	3-10
54			Front Brake Drums	3-9
55	X		Rear Brake Drums	3-9
56			Front Brake Lining	3-9
57	X		Rear Brake Lining	3-9
58			Wheel Cylinders	3-9, M3-3
59			Mechanical Components	3-8, 9, M3-1
60			Proportioning Valve	3-11

RECREATIONAL VEHICLE				
No.	R	C	Item	Ref #
80			CSA Z-240 Standard Approval Number	11-1
81			Manitoba Labour Z-240 Standard Approval Number	11-1

BODY EXTERIOR				
No.	R	C	Item	Ref #
23			Headlamp, Operation	6-1
24			Headlamp Aim	6-4, M6-3
25			Turn Signal Lamps	6-1
26			Parking Lamps	6-1
27			Side Marker Lamps	6-1
28			Reflex Reflectors	6-2
29			Back-up Lamps	6-1
30			Tail Lamps	6-1

Brake Lining Thickness: F 9/32, R 1/32
 Drum/Rotor Measurement: 1.156, 1.743 Right
 Axle 1: 9/32, Axle 2: 3/32
 Axle 1: 1.167, Axle 2: 1.779 Left

- THIS INSPECTION IS NOT A WARRANTY -
 This inspection addresses safety components within the Provincial Vehicle Inspection Handbook but does not guarantee these components will comply with the standards for any unspecified future period of time.
 To determine if this vehicle has an open safety recall issued by the vehicle manufacturer, please search the Motor Vehicle Safety Recalls Database on Transport Canada's website at <http://www.tc.gc.ca/> or contact Transport Canada at 1-800-333-0510.

REMARKS:

Mark 'X' under 'R' when item rejected
 Mark 'XX' under 'R' when vehicle out-of-service
 Mark 'X' under 'C' when item corrected
 Ref # indicates corresponding manual section
 A circled item # indicates advisement only

I am aware that the above-noted vehicle is unsafe to be operated on a highway due to the noted equipment defects. I undertake to prevent this vehicle from being operated on a highway until the repairs or adjustments have been made to restore it to safe condition and a qualified mechanic has re-inspected the vehicle.
 Vehicle Received without repairs by: _____ Signature: _____ Date: _____